



CV60: Install RFlexCE

The following procedures are for a Intermec CV60 with Windows CE 4 2 installed. (Note: T=Terminal, PC=Computer). You will need the following:

- **USB Drive.**
- **RFlex CE Software from Genesta.**

Copy RFlexCE Files to Terminal

- [PC] Copy the 2 folders (**Genesta** and **RFlex**) to USB drive.
- [PC / T] Remove the USB drive from the PC and insert it into one of the USB ports on the CV60. It will show up in Windows Explorer as a folder called **Hard Disk**.
- [T] Tap **Start** icon in the bottom left corner, then tap **Programs** and tap **Windows Explorer** from the list.
- [T] Copy both the Genesta and RFlex folders from the USB drive (**Hard Disk**) to the **File Store** folder.

Install RFlexCE

- [T] While still in Windows Explorer, go to the **File Store\Genesta** folder.
- [T] Install each .CAB file by double-tapping them in the following order (allow each install to run to conclusion and accept any defaults if prompted):
 - ✓ Netcf.all.wce4.x86.cab
 - ✓ RFlex_WCE4.X86.CAB
 - ✓ RFlexEtc_WCE4.X86.CAB
 - ✓ LCLKeyboard.CAB

Run RFlexCE

- [T] Tap **Start** icon, then **Programs**, then **RFlex**, or double-tap the **RFlex** icon on the desktop to start the application.
- [T] Tap **Configure** at the bottom of the display.
- [T] Enter the password "**rfctrl**".
- [T] Enter the Host IP Address, the Host Port, enter the Unit ID for the terminal (you should get these values from your supervisor) and set the Communication timeout value (15 seconds is standard).
- [T] Tap **OK** to save the settings and return to the Logon screen.



- [T] Tap **Logon** bar. You should be taken to the “RFlex License” screen. Copy down the terminal model number, serial number, and Product ID from the display. Call Genesta to request a key (phone number is on-screen). When you get the key, enter it into the “License Key” field and tap **OK**. Tap **OK** on the “Thank You” box.
- [T] Tap **Logon** bar. If the wireless settings and the RFlex host settings are all correct, you should see the opening “TRICEPS login” screen. Log in and begin work.

Note: If the function keys do not seem to be not working, make sure that RFlex window has focus on it (“RFlex” on the window title should be in white)

Barcode Scanner SR60 Setup Instructions

- Plug SR60 into **COM1** port on CV60
- Tap **Start** icon in bottom left corner, then **Settings**, then **Control Panel**. Double-tap the **Intermec Settings** icon. Turn the scanner on by tapping **Data Collection**, then **Tethered Scanner (COM1)**. Tap box next to **Enable scanner port** if it is not already checked. Save the settings by tapping **File** at the top, then tapping **Save Settings** from the list. SR60 and CV60 will beep. Tap **File** again, then **Exit** from the list. Tap **X** in the top right corner to close the Control Panel.